



6kW Ecodan on 19/03/2025. Severe low-output & low discharge temperature for about 20mins



[Grab your reader's attention with a great quote from the document or use this space to emphasize a key point. To place this text box anywhere on the page, just drag it.]